

Viatic UK

Westfield Business Centre
Radstock, Bath, BA3 4BH

Tel: 01761 409107

Fax: 01761 409111

info@viatic-uk.com

www.viatic-uk.com

VIATEC: Ironbond HA104

High Strength Early Setting Mortar

A collapsed gully repaired using Viafix and Ironbond HA104 – two of Viatic's all weather reactive maintenance products.



A collapsed gully causes problems on a busy road. Intense rainfall required sandbagging to reduce heavy flow.



Viatic's **Ironbond HA104** early cure high strength mortar



The gully chamber has been rebuilt and the frame bedded with **Ironbond HA104**.



Continued heavy rainfall refills the excavation but poses no problem for **Viafix** - extreme performance cold lay asphalt, which can be laid in or underwater and in freezing conditions.



Permanent gully reinstatement using Viatic's **Ironbond HA104** and **Viafix** carried out in extreme weather conditions.

Viatic

Tel: 01761 409107

Web: www.viatic-uk.com see live reports on YouTube & Vimeo